



CITY OF HOUSTON

Fire Marshal, Life Safety Bureau

Houston Fire Department

1801 Smith St., 6th Floor Houston, Texas 77002

832-394-6900 / fax: 832-394-6911

GONZALEZ, CARLOS
2900 NORTH LOOP WEST # 160
HOUSTON, TX 77092

Project No: **13121977**
Report Date: 02-DEC-2013
Compliance Date: 28-MAY-2014
Subject to Re-Inspection

<<INSPECTION REPORT>>

Your attention is respectfully called to the violation of the provisions of the City of Houston Fire Code as indicated herein, on the premises located at:

1) HFC 105.8.2 - Re-inspection fee 2800 NORTH LOOP WEST

Whenever it becomes necessary to make a re-inspection (after the initial inspection and one follow-up inspection under Section 105.8 of the city fire code), because of faulty material, faulty workmanship, or incomplete work, or for any other reason, the owner, operator, or lessee, shall pay for each re-inspection.

Failure on your part to comply with the indicated violations will subject you to the penalties prescribed by law for such violations.

Inspecting Officer Signature	_____	Date	_____
Copy Received By Signature	_____	Date	_____
Followup Inspection	_____	Date	_____
Scheduled Reinspection Date	_____	Date	_____
Scheduled Reinspection Date	_____	Date	_____
Inspection Complete	_____	Date	_____